


Home Test

Visual Uric Acid Test Kit

• QUCARE Self Blood Uric Acid

This test measures the amount of Blood Uric Acid for early detection of gout levels. Hyperuricemia can cause crystals of uric acid (or urate) to form.



- 3 - 14 mg/dl (178 - 833 umol/L)
- Only capillary blood
- 2 minutes
- 10 uL(Capillary included)


How to use a test kit

Step 1)



- Wash and Dry your hands

Step 2)



- Prick your finger and get a blood sample (only 10uL)

Step 3)



- Apply the blood sample and check the test result after 2 minutes.

Ordering Information

Product	Cat.No	TESTS/KIT	Package	Test Parameters
QUCARE Self Total cholesterol	6407	2	Pouch	Total cholesterol
QUCARE Self Blood Uric Acid	6417	2	Pouch	Uric Acid